

## **REINFORCING NOTES:**


- 1. SEE "GENERAL NOTES" FOR REINFORCING REQUIREMENTS.
- 2. SEE "TYPICAL POST-TENSIONED SLAB DETAILS" FOR ADDITIONAL INFORMATION.
- 3. SLAB REINFORCING SHALL BE PLACED IN THE FOLLOWING SEQUENCE: BOT BARS IN DIRECTION OF DISTRIBUTED TENDONS BOT BARS IN DIRECTION OF BANDED TENDONS TOP BARS IN DIRECTION OF BANDED TENDONS TOP BARS IN DIRECTION OF DISTRIBUTED TENDONS
- 4. (RX) INDICATES STUD RAIL. STUD RAILS SHALL BE PLACED AT ALL COLUMNS. SEE "TYPICAL STUD RAIL REINFORCEMENT AT COLUMNS" DETAIL AND STUD RAIL
- 5. SEE "TYPICAL CONCRETE OPENINGS AND EMBEDMENTS" FOR ADDITIONAL REINFORCEMENT REQUIREMENTS. NOTIFY STRUCTURAL ENGINEER OF ANY OPENINGS NOT SHOWN ON THE STRUCTURAL DRAWINGS FOR WHICH THE TYPICAL DETAILS DO NOT APPLY. ADDITIONAL REINFORCEMENT MAY BE REQUIRED.
- 6. WHERE BAR LENGTH CANNOT BE ACHIEVED DUE TO SLAB EDGE, HOOK BAR.
- 7. WHERE NOTES AS "HOOKED", PROVIDE 90 OR 180 DEGREE HOOK AS SHOWN ON PLAN. NOTED BAR LENGTH IS LENGTH OF STRAIGHT PORTION OF BAR.
- 8. PROVIDE INTEGRITY BOTTOM BARS PER STUD RAIL SCHEDULE AT ALL COLUMNS. CENTER REINFORCEMENT ON COLUMNS AND PLACE INTEGRITY BARS EACH WAY WITHIN COLUMN VERTICAL REINFORCEMENT. TRIM AND HOOK AT SLAB EDGE AS REQUIRED.
- 9. \* INDICATES DIAPHRAGM REINFORCEMENT THAT IS PART OF THE LATERAL FORCE RESISTING SYSTEM AND IS IN ADDITION TO OTHER BARS SHOWN. THIS REINFORCEMENT SHALL BE CENTERED IN SLAB MID-DEPTH, UNO. REINFORCEMENT SHALL MEET CENTER-TO-CENTER SPACING OF 3db BUT NOT LESS THAN 3-INCHES, UNLESS NOTED OTHERWISE. LAP Lsb AS REQUIRED, STAGGER LAPS.


## TOWER C - LEVEL 2 - REINFORCEMENT PLAN 1/8" = 1'-0"

- 10. WHERE NOTE APPLIES, REINFORCEMENT IS DIAPHRAGM REINFORCEMENT THAT IS PART OF THE LATERAL FORCE RESISTING SYSTEM AND IN ADDITION TO OTHER BARS SHOWN. REINFORCEMENT IS TO BE PLACED WITHIN VERTICALS OF COLUMN NEAR GRID C.3/C.F. REINFORCEMENT SHALL BE CENTERED IN SLAB MID-DEPTH. REINFORCEMENT SHALL MEET CENTER-TO-CENTER SPACING OF 3db BUT NOT LESS THAN 3-INCHES, UNLESS NOTED OTHERWISE. LAP SPLICE IS NOT PERMITTED; PROVIDE MECHANICAL COUPLER IF NECESSARY.
- 11. WHERE NOTE APPLIES, REINFORCEMENT IS TO BE PLACED WITHIN VERTICALS OF COLUMN NEAR GRID C.6/C.G, WITH TERMINATOR AT SOUTH END. REINFORCEMENT SHALL BE CENTERED IN SLAB MID-DEPTH. REINFORCEMENT SHALL MEET CENTER-TO-CENTER SPACING OF 3db BUT NOT LESS THAN 3-INCHES, UNLESS NOTED OTHERWISE. LAP SPLICE IS NOT PERMITTED; PROVIDE MECHANICAL COUPLER IF NECESSARY.

PT TOP REINFORCEMENT SCHEDULE						
MARK	REINFORCING	REMARKS				
PT1	(6) #5x10'-0"					
PT2	(6) #5x15'-0"					
PT3	(8) #5x15'-0"					
PT4	(12) #5x10'-0"					
PT5	(10) #5x15'-0"					
PT6	(18) #6x12'-0" @ 5"	STAGGER 3'-0"				
PT7	(14) #5x10'-0"					
PT9	(14) #6x15'-0"					
PT11	(13) #6x15'-0"					
PT12	(10) #5x12'-0"					
PT30	#5x10'-0"@ 15"					
PT32	#6x12'-0"@ 6"					
PT50	(4) #5x6'-8"	HOOK AT END				
PT51	(6) #5x6'-8"	HOOK AT END				
PT52	(10) #5x9'-2"	HOOK AT END				
PT54	(6) #5x14'-2"	HOOK AT END				
PT56	(16) #5x11'-2"	HOOK AT END				
PT57	(10) #5x14'-2"	HOOK AT END				
PT60	(12) #5x9'-2"	HOOK AT END				
PT80	#5x11'-2" @ 10"	HOOK AT END				
PT81	#5x6'-8" @ 10"	HOOK AT END				
PT82	#6x9'-0"@ 4"	HOOK AT END				
PT83	#6x9'-0" @ 6"	HOOK AT END				

PT TOP REINFORCEMENT SCHEDULE				PT BOTTOM REINFORCEMENT SCHEDUL		
//ARK	REINFORCING	REMARKS		MARK	REINFORCING	REMARK
PT1	(6) #5x10'-0"			PB1	#5x10'-0" @ 6"	
PT2	(6) #5x15'-0"			PB4	#4x6'-10" @ 12"	HOOK AT EN
PT3	(8) #5x15'-0"			PB5	#5x6'-8" @ 6"	HOOK AT EN
PT4	(12) #5x10'-0"			PB7	#5x20'-0" @ 12"	
PT5	(10) #5x15'-0"			PB8	#7x20'-0" @ 12"	
PT6	(18) #6x12'-0" @ 5"	STAGGER 3'-0"		PB9	#7x20'-0" @ 6"	
PT7	(14) #5x10'-0"			PB10	#6x20'-0" @ 6"	
PT9	(14) #6x15'-0"			PB13	#5x15'-0" @ 24"	
PT11	(13) #6x15'-0"			PB14	#5x15'-0" @ 12"	
PT12	(10) #5x12'-0"			PB15	#7x10'-0" @ 8"	
PT30	#5x10'-0"@ 15"			PB16	#7x6'-4" @ 8"	HOOK AT EN
PT32	#6x12'-0"@ 6"			PB17	#5x10'-0" @ 12"	
PT50	(4) #5x6'-8"	HOOK AT END		PB18	#7x10'-0" @ 12"	
PT51	(6) #5x6'-8"	HOOK AT END				
PT52	(10) #5x9'-2"	HOOK AT END				
	<del>-  </del>		1			





Kundig

MAGNUSSON KLEMENCIC ASSOCIATES Structural + Civil Engineers Seattle Chicago www.mka.com 206 292 1200

principal architect_	
project manager_	
checked by_	
	20052
_	05/17/2024
revisions:	
	·

NOT FOR CONSTRUCTION 05/17/2024

5 01/07/2025 ASI-007

no. date

11/18/2022 95% CD

04/08/2024 IFC SET 1 OF 3

TOWER C LEVEL 2 REINFORCING PLAN

S2.C.12.R